

Republic of the Philippines PHILIPPINE HEALTH INSURANCE CORPORATION

POMM-P- 007

JOB ORDER

(Non - Inventoriable Items)

OFFICE/DEPARTMENT: PRO 1

Supplier: ASIA MOTOR WORKS

Address: San Fernando City, La Union

Work Order No.: 22 02

Date: 3/22/2022

Tel. Fax No .:

(072) 888-4422

Term of Payment: Charge

Supplier Registered with:

111-204-879-000 NV

Mode of Procurement: Negotiated Procurement-

Small Value Procurement

NO.	QTY	UNIT	SERVICE DETAILS	UNIT PRICE	TOTAL AMOUNT
Profesion (SA) Page STS(A) (SA)			Repair and Maintenance of Toyota Innova SHU-882 Alternator Repair		
i. Delive op ni Use sil verve	1	рс	Alternator Pully	4,500.00	4,500.00
an a	1	рс	Alternator Bearing Big	850.00	850.00
Made a	1	рс	Alternator Bearing Small	750.00	750.00
Jarra .	4	pcs	Idle Bearing	650.00	2,600.00
r Tarana Mar	reed of laws	Total - Materia		Materials	8,700.00
in etae masan	e territa		Labor	1,800.00	1,800.00
			אאאאאאאאאאאאאאאאאאאאאאאאאאאאאאאאאאאאא	TOTAL-L&M	10,500.00
			Less: TAX		ela il Norman espera
	V 2		VAT (1%)	105.00	
			EWT (2%)	210.00	315.00
rilli Armi			PR No. 22-0125-0005 (50213060)	Total - Net of	71 Kuji i t
09E A. W	39/ES		Requesting Unit: LHIO La Union	Tax	10,185.00

Terms & Conditions

em/s shall be delivered and accepted by the Procurement Section at 15th Floor, Room 1503 Citystate Ctr. Bldg. Pasig City.

divery Receipt and Sales Invoice shall be required for one-time complete delivery of the goods.

5. Defective, incompatible or non-compliant of goods as to specification when the series of the compliant of goods as to specification when the series of layout/design presented by the supplier does not be the series of layout/design presented by the supplier does not be the series of layout/design presented by the supplier does not be the series of layout/design presented by the supplier does not be the series of layout/design presented by the supplier does not be the series of layout/design presented by the supplier does not be the series of layout/design presented by the supplier does not be the series of layout/design presented by the supplier does not be the series of layout/design presented by the supplier does not be the series of layout/design presented by the supplier does not be the series of layout/design presented by the supplier does not be the series of layout/design presented by the supplier does not be the series of layout/design presented by the supplier does not be the series of layout/design presented by the supplier does not be the series of layout/design presented by the supplier does not be the series of layout/design presented by the supplier does not be the series of layout lay

to cancel the Job Order (JO)

7. Payment shall be made in full subject to corresponding government taxes within fifteen (15) working days upon receipt of Certificate of Acceptence and inspection Report

MAR 28 2022

Very truly yours,

rufied Budger Available:

JOSE A. MONES

Funds Available

CYNTHIA S. SANTO Division Chief IV / MSD Chi

Fiscal Controller III

EDWARD Q. ESPIRITU AO IV / OIC-OFMS Chief

Regional Vice President

With in the COB:

Tixpense Code:

Bdggt

Remarks

w uni

3-24-22 Date

Signature over Printed Name

of Supplier / Representative

Recevied copy of J.O. on

^{1.} The agency shall impose penalty in an amount equivalent to 1/10 on one (1%) percent of the total value of undelivered order for each day of the delay as liquidated damages.

² if the date of receipt of the Job Order (J.O.) by the dealer is not indicated, it shall be deemed received on the day it was acknowledged to have been received by a representative either through fax or e-mail.

^{3.} Delivery of the above item/s shall be made within the prescribed schedule dates. Suppliers are advised to inform Procurement Section at least two (2) days before the delivery. Use of elevator shall be from 9:00AM to 11:30 AM and 1:30pm to 3:00PM during Mon/Wed/Fri (MWF).